





# Filter Fan Hood OUNTING INSTRUCTIONS




1. Drill 4 holes centred around the filter fan.



2. Fix the mounting brackets using the screws / washers / nuts provided.  
Torque: 4.5 Nm / 40 Lb-In



3. Assemble the hood by pushing towards the panel and then firmly downwards.



Stainless steel hoods must be used on the flat surface of Type 1, 2, 3, 3X, 3R, 3RX, 3S, 3SX, 4\*, 4X\*, 5, 12, 12K or 13 enclosures